










# PILE GROUP (TOWER) MULTI-MEDIA CAP PENETRATION




## **RESTORATION OF CAP BELOW PILE GROUP**




# **COMPLETED FOUNDATION**



### PILE BOOT DETAIL (BOOT SEALS MEMBRANE TO PILE WALL)





FRM.

Figure 2 Perimeter Construction Monitoring Locations

